BEAST TPC Status

- Humu taken out of FWD tunnel and placed in ARICH clean room as spare
- Iiwi put in its place (²¹⁰Po sources moved from Humu)
- HV currents fixed with existing cables (matches other TPCs now)
- Communication is stable
- Trigger initially not communicating, now fixed
- External trigger still not firing (internal is)

